

## Building Committee Report 2018

### REPAIRS DONE IN 2018

New roof over kitchen area. Due to water damage the kitchen closet needed ceiling repairs, new shelves and painting. Rain gutters were repaired and new ones installed where needed.

New carpet for church

Exterior arches on the east side of the church building reinforced with 5' X 5/8" x 8' steel braces with 8" bolts and three 5/8" bolts to the footing. West side arches were done 2017.

Parking lot stripes and bumpers painted (Pastor Dexter)

### NEEDED REPAIRS

The windows leak in the sanctuary, to fix the problem the windows need caulking and new quarter round molding to replace rotted ones. Due to the leaks the interior arched trusses on the east side of the church are rotted up to 3" off the floor.

In the Fellowship Hall storage room two windows on the west side need new window frames and new glass.

The big window in the vestibule, facing south, needs repairs.